

# Memorandum



Date: January 20, 2012  
To: Members of the Public Safety Committee  
Subject: Administrative (Fire) Reports

This is an informational memo to provide the Public Safety Committee with a brief description of the December 2011 fire reports on Monday, January 23, 2012.

During this period, there were no "3-Alarm or greater" fires. There was a "1-Alarm" vehicle fire with a fatality. There were two "2-Alarm" fires and there were two "1-Alarm" with Injury fires.

The fire reports are attached.



A.C. Gonzalez  
First Assistant City Manager

## Attachment

c: Honorable Mayor and Members of the Dallas City Council  
Mary K. Suhm, City Manager  
Rosa Rios, Acting City Secretary  
Thomas P. Perkins, Jr., City Attorney  
Craig D. Kinton, City Auditor  
C. Victor Lander, Administrative Judge  
Jill A. Jordan, P.E., Assistant City Manager  
Ryan S. Evans, Assistant City Manager  
Forest E. Turner, Assistant City Manager  
Joey Zapata, Assistant City Manager  
Jeanne Chipperfield, Chief Financial Officer  
Frank Libro, Public Information Office  
Stephanie Cooper, Assistant to the City Manager

# Public Safety Committee

## Fire Report

### December 2011

DATE	ADDRESS	COUNCIL DISTRICT	TYPE	CAUSE	LOSS/INSURED?	ALARMS
1. 11/28/11	4410 Newmore Avenue	District 14	Pile of wood in Backyard	Child with Heat Source	\$0.00 No	1 Alarm <b>Injury</b>
2. 11/28/11	3637 Trinity Mills Road #321	District 12	3-Story Frame Apartments	Unattended Cooking	\$1,500 No	1 Alarm <b>Injury</b>
3. 12/02/11	3500 Gaston Avenue	District 2	6-Story Brick Commercial	Under Investigation	\$33,000 Yes	3 Alarms
4. 12/06/11	8933 Senate Street #2054	District 7	2-Story Brick Apartments	Under Investigation	\$15,000 No	1 Alarm <b>Injury</b>
5. 12/06/11	1826 Billie Drive	District 5	1-Story Brick Residence	Unspecified Electrical Short Circuit (Fixed Wiring)	\$40,000 Unknown	1 Alarm <b>Fatality</b>
6. 12/06/11	8750 North Central Expressway	District 13	20-Story Metal Commercial	Transformer Malfunction	\$10,000 No	2 Alarms
7. 12/12/11	8725 Lullwater Drive	District 10	1-Story Brick Residence	Unspecified Electrical Short Circuit (Fixed Wiring)	\$116,500 Yes	1 Alarm <b>Injury</b>
8. 12/13/11	5308 Miller Avenue	District 14	1-Story Frame Residence	Unspecified Electrical Short Circuit (Fixed Wiring)	\$182,500 Unknown	1 Alarm <b>Injury</b>
9. 12/13/11	10075 Royal Lane #1047	District 10	2-Story Frame Apartments	Careless Use of Candle	\$188,000 No	3 Alarms <b>Injury</b>
10. 12/14/11	3330 Webb Chapel Extension #2223	District 6	2-Story Brick Apartments	Careless Smoking	\$15,000 No	1 Alarm <b>Injury</b>
11. 12/16/11	1301 Main Street #A	District 14	4-Story Masonry Commercial	Incendiary	\$20,000 Yes	3 Alarms
12. 12/18/11	300 (Block) Town Creek Drive	District 4	Vehicle	Incendiary	\$6,000 Unknown	1 Alarm <b>Fatalities</b>
13. 12/27/11	2015 Orleans Street	District 2	1-Story Frame Residence	Combustibles Too Close To Heat Source	\$31,210 Unknown	1 Alarm <b>Injury</b>
14. 12/27/11	6834 Larmanda Street #239	District 9	2-Story Brick Apartments	Unspecified Electrical Short Circuit (Non-Fixed Wiring)	\$100,000 No	2 Alarms
15. 12/31/11	2811 Painted Trail	District 8	1-Story Frame Residence	Incendiary	\$60,000 Unknown	1 Alarm <b>Injury</b>

## One Alarm Fire (Injury)

<b>Date of Fire:</b>	November 28, 2011	<b>Time of Fire</b>	6:56 PM										
<b>Incident Number</b>	2011-233082	<b>Response Time</b>	4 Min. 11 Sec.										
<b>Location</b>	4410 Newmore Avenue	<b>Service Area</b>	Northwest										
<b>Bldg. Type</b>	Backyard	<b>Council District</b>	14										
<b>Owner</b>	Kevin Keane	<b>Injuries (Firefighter/ Civilian)</b>	One Civilian Injury										
<b>Occupant/ Business Name</b>	Kevin Keane												
<b>Fire Alarm System</b>	N/A	<b>Operational</b>	N/A										
<b>Cause</b>	Child with Heat Source												
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: center;">\$0.00</td> <td style="text-align: center;">\$0.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: center;">\$0.00</td> <td style="text-align: center;">\$0.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: center; border-top: 1px solid black;">\$0.00</td> <td style="text-align: center; border-top: 1px solid black;">\$0.00</td> </tr> </tbody> </table>		<u>Value</u>	<u>Damage</u>	Building:	\$0.00	\$0.00	Content:	\$0.00	\$0.00	<b>TOTAL</b>	\$0.00	\$0.00
	<u>Value</u>	<u>Damage</u>											
Building:	\$0.00	\$0.00											
Content:	\$0.00	\$0.00											
<b>TOTAL</b>	\$0.00	\$0.00											
<b>Narrative</b>	<p>This accidental fire was the result of a child with a heat source. An ignitable liquid was poured onto a smoldering pile of wood in the back yard. A fire injury occurred as a result of this fire. An 11-year old female sustained second and third degree burns to her left calf and knee when she poured gasoline on this fire. She was transported to Parkland Hospital by Rescue 35. This is not an insured loss. Engine 42 was the first unit to respond to this incident.</p>												

### One Alarm Fire (Injury)

<b>Date of Fire:</b>	November 28, 2011	<b>Time of Fire</b>	7:26 PM												
<b>Incident Number</b>	2011-233095	<b>Response Time</b>	3 Min. 31 Sec.												
<b>Location</b>	3637 Trinity Mills Road #321	<b>Service Area</b>	North Central												
<b>Bldg. Type</b>	3-Story Frame Apartments	<b>Council District</b>	12												
<b>Owner</b>	Mid-America Apartments of Texas	<b>Injuries (Firefighter/Civilian)</b>	One Civilian Injury												
<b>Occupant/ Business Name</b>	Callan Rattase Deer Run Apartments														
<b>Fire Alarm System</b>	Unknown	<b>Operational</b>	Unknown												
<b>Cause</b>	Unattended Cooking														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: right;"><u>Value</u></th> <th style="text-align: right;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$8,749,990.00</td> <td style="text-align: right;">\$1,500.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$15,000.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$8,764,990.00</td> <td style="text-align: right; border-top: 1px solid black;">\$1,500.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$8,749,990.00	\$1,500.00	Content:	\$15,000.00	\$0.00	<b>TOTAL</b>	\$8,764,990.00	\$1,500.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$8,749,990.00	\$1,500.00													
Content:	\$15,000.00	\$0.00													
<b>TOTAL</b>	\$8,764,990.00	\$1,500.00													
<b>Narrative</b>	<p>This accidental fire was caused when an unattended pan of grease caught fire. This fire caused damage to the stove, vent hood assembly, and adjacent cabinetry in the kitchen. A fire injury occurred as a result of this fire. An 18-year old female sustained second degree burns to her left hand and wrist as she attempted to extinguish this fire. She attempted to extinguish this fire by removing the burning pan from the stove to the sink. She was transported to Parkland Hospital by Rescue 10. It is unknown if this apartment had a properly installed fire alarm system. This is not an insured loss. Engine 10 was the first unit to respond to this incident.</p>														

### Three Alarm Fire

<b>Date of Fire:</b>	December 2, 2011	<b>Time of Fire</b>	6:44 PM												
<b>Incident Number</b>	2011-235727	<b>Response Time</b>	1 Min. 38 Sec.												
<b>Location</b>	3500 Gaston Avenue	<b>Service Area</b>	Central												
<b>Bldg. Type</b>	6-Story Brick Commercial	<b>Council District</b>	2												
<b>Owner</b>	Baylor University Medical Center	<b>Injuries (Firefighter/Civilian)</b>	N/A												
<b>Occupant/ Business Name</b>	Baylor University Medical Center Baylor University Medical Center														
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	Yes												
<b>Cause</b>	Under Investigation														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 50%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building: \$13,360,000.00</td> <td></td> <td style="text-align: right;">\$25,000.00</td> </tr> <tr> <td>Content: \$10,000,000.00</td> <td></td> <td style="text-align: right;">\$8,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right;"><b>\$23,360,000.00</b></td> <td style="text-align: right;"><b>\$33,000.00</b></td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building: \$13,360,000.00		\$25,000.00	Content: \$10,000,000.00		\$8,000.00	<b>TOTAL</b>	<b>\$23,360,000.00</b>	<b>\$33,000.00</b>	
	<u>Value</u>	<u>Damage</u>													
Building: \$13,360,000.00		\$25,000.00													
Content: \$10,000,000.00		\$8,000.00													
<b>TOTAL</b>	<b>\$23,360,000.00</b>	<b>\$33,000.00</b>													
<b>Narrative</b>	<p>The cause of this fire is under investigation at this time. There are no suspects or witnesses at this time. The fire started in the men's locker room in the basement of the Truett Building of this hospital occupancy. The fire sprinkler system contained and confined the fire to the room of origin. This hospital has a properly installed operational fire alarm system that warned the occupants of the fire. This is an insured loss. Engine 3 was the first unit to respond to this incident.</p>														

## One Alarm Fire (Injury)

<b>Date of Fire:</b>	December 6, 2011	<b>Time of Fire</b>	12:57 AM												
<b>Incident Number</b>	2011-238108	<b>Response Time</b>	3 Min 17 Sec.												
<b>Location</b>	8933 Senate Street #2054	<b>Service Area</b>	Northeast												
<b>Bldg. Type</b>	2-Story Brick Apartments	<b>Council District</b>	7												
<b>Owner</b>	A S Management	<b>Injuries (Firefighter/ Civilian)</b>	One Civilian Injury												
<b>Occupant/ Business Name</b>	Billy Compton St. Frances Apartments														
<b>Fire Alarm System</b>	None	<b>Operational</b>	N/A												
<b>Cause</b>	Under Investigation														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: right;"><u>Value</u></th> <th style="text-align: right;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$1,000,000.00</td> <td style="text-align: right;">\$10,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$15,000.00</td> <td style="text-align: right;">\$5,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$1,015,000.00</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$15,000.00</b></td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$1,000,000.00	\$10,000.00	Content:	\$15,000.00	\$5,000.00	<b>TOTAL</b>	<b>\$1,015,000.00</b>	<b>\$15,000.00</b>	
	<u>Value</u>	<u>Damage</u>													
Building:	\$1,000,000.00	\$10,000.00													
Content:	\$15,000.00	\$5,000.00													
<b>TOTAL</b>	<b>\$1,015,000.00</b>	<b>\$15,000.00</b>													
<b>Narrative</b>	<p>The cause of this fire is under investigation at this time. This fire started in the bedroom and caused damage to the entire apartment. A fire injury occurred as a result of this fire. A 47-year old female sustained second and third degree burns to her entire torso. She was transported to Parkland Hospital by Rescue 19. This is not an insured loss. Engine 53 was the first unit to respond to this incident.</p>														

### One Alarm Fire (Fatality)

<b>Date of Fire:</b>	December 6, 2011	<b>Time of Fire</b>	2:23 AM												
<b>Incident Number</b>	2011-238146	<b>Response Time</b>	3 Min. 31 Sec.												
<b>Location</b>	1826 Billie Drive	<b>Service Area</b>	Southwest												
<b>Bldg. Type</b>	1-Story Brick Residence	<b>Council District</b>	5												
<b>Owner</b>	Marvin Dorsey	<b>Injuries (Firefighter/ Civilian)</b>	One Civilian Fatality												
<b>Occupant/ Business Name</b>	Marvin Dorsey														
<b>Fire Alarm System</b>	None	<b>Operational</b>	N/A												
<b>Cause</b>	Unspecified Electrical Short Circuit (Fixed Wiring)														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$51,000.00</td> <td style="text-align: right;">\$30,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$20,000.00</td> <td style="text-align: right;">\$10,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right;"><b>\$71,000.00</b></td> <td style="text-align: right;"><b>\$40,000.00</b></td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$51,000.00	\$30,000.00	Content:	\$20,000.00	\$10,000.00	<b>TOTAL</b>	<b>\$71,000.00</b>	<b>\$40,000.00</b>	
	<u>Value</u>	<u>Damage</u>													
Building:	\$51,000.00	\$30,000.00													
Content:	\$20,000.00	\$10,000.00													
<b>TOTAL</b>	<b>\$71,000.00</b>	<b>\$40,000.00</b>													
<b>Narrative</b>	<p>This accidental fire was caused by an unspecified electrical short circuit of the fixed wiring. The wiring was connected to the electrical panel in a bedroom closet. The fire ignited the adjacent bed and caused severe damage to the residence and its contents. A fire fatality occurred as a result of this fire. An 85-year old black male was pronounced dead at Methodist Central Hospital from injuries sustained in this fire. The cause of death is pending the results of an autopsy by the Medical Examiner. He was transported to Methodist Central Hospital by Rescue 49. This residence did not have a properly installed fire alarm system. Insurance information is unknown at this time. Engine 49 was the first unit to respond to this incident.</p>														

## Two Alarm Fire

<b>Date of Fire:</b>	December 6, 2011	<b>Time of Fire</b>	4:07 PM												
<b>Incident Number</b>	2011-238506	<b>Response Time</b>	44 Sec.												
<b>Location</b>	8750 North Central Expressway	<b>Service Area</b>	Northeast												
<b>Bldg. Type</b>	20-Story Metal Commercial	<b>Council District</b>	13												
<b>Owner</b>	8750 NCE Dallas LLC.	<b>Injuries (Firefighter/Civilian)</b>	N/A												
<b>Occupant/ Business Name</b>	8750 NCE Dallas LLC. Northpark Central Tower														
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	Yes												
<b>Cause</b>	Transformer Malfunction														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 50%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$40,000,000.00</td> <td style="text-align: right;">\$10,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$20,000,000.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right;"><b>\$60,000,000.00</b></td> <td style="text-align: right;"><b>\$10,000.00</b></td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$40,000,000.00	\$10,000.00	Content:	\$20,000,000.00	\$0.00	<b>TOTAL</b>	<b>\$60,000,000.00</b>	<b>\$10,000.00</b>	
	<u>Value</u>	<u>Damage</u>													
Building:	\$40,000,000.00	\$10,000.00													
Content:	\$20,000,000.00	\$0.00													
<b>TOTAL</b>	<b>\$60,000,000.00</b>	<b>\$10,000.00</b>													
<b>Narrative</b>	<p>This accidental fire was caused by an unspecified malfunction in the transformers of the elevator motor. Fire damage was confined to the transformers. This commercial high rise office building was equipped with a properly installed operational fire alarm system that warned the occupants and aided in their escape. This is not an insured loss. Engine 37 was the first unit to respond to this incident.</p>														

## One Alarm Fire (Injury)

<b>Date of Fire:</b>	December 12, 2011	<b>Time of Fire</b>	10:04 PM												
<b>Incident Number</b>	2011-242652	<b>Response Time</b>	2 Min. 25 Sec.												
<b>Location</b>	8725 Lullwater Drive	<b>Service Area</b>	Northeast												
<b>Bldg. Type</b>	1-Story Brick Residence	<b>Council District</b>	10												
<b>Owner</b>	Dennie Haynes	<b>Injuries (Firefighter/ Civilian)</b>	One Civilian Injury												
<b>Occupant/ Business Name</b>	Dennie Haynes														
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	Yes												
<b>Cause</b>	Unspecified Electrical Short Circuit (Fixed Wiring)														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 20%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$179,370.00</td> <td style="text-align: right;">\$86,500.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$70,000.00</td> <td style="text-align: right;">\$30,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$249,370.00</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$116,500.00</b></td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$179,370.00	\$86,500.00	Content:	\$70,000.00	\$30,000.00	<b>TOTAL</b>	<b>\$249,370.00</b>	<b>\$116,500.00</b>	
	<u>Value</u>	<u>Damage</u>													
Building:	\$179,370.00	\$86,500.00													
Content:	\$70,000.00	\$30,000.00													
<b>TOTAL</b>	<b>\$249,370.00</b>	<b>\$116,500.00</b>													
<b>Narrative</b>	<p>This accidental fire was caused by an unspecified electrical short circuit of the fixed wiring in the attic above the garage. The fire destroyed the roof above the garage and the contents of the garage. A boat and vehicle parked outside of the garage were also exposed to this fire. A fire injury occurred as a result of this fire. A 62-year old male sustained second degree burns to the top of his head and both hands when he attempted to rescue his dog from the fire. He was treated at the scene and released. This residence had a properly installed operational fire alarm system. This is an insured loss. Engine 48 was the first unit to respond to this incident.</p>														

## One Alarm Fire (Injury)

<b>Date of Fire:</b>	December 13, 2011	<b>Time of Fire</b>	5:29 AM												
<b>Incident Number</b>	2011-242789	<b>Response Time</b>	3 Min 27 Sec.												
<b>Location</b>	5308 Miller Avenue	<b>Service Area</b>	Central												
<b>Bldg. Type</b>	1-Story Frame Residence	<b>Council District</b>	14												
<b>Owner</b>	Annette Sparkman	<b>Injuries (Firefighter/ Civilian)</b>	One Civilian Injury												
<b>Occupant/ Business Name</b>	Maria Flores														
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	Yes												
<b>Cause</b>	Unspecified Electrical Short Circuit (Fixed Wiring)														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 20%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$219,280.00</td> <td style="text-align: right;">\$175,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$15,000.00</td> <td style="text-align: right;">\$7,500.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$234,280.00</td> <td style="text-align: right; border-top: 1px solid black;">\$182,500.00</td> </tr> </tbody> </table>		<u>Value</u>	<u>Damage</u>	Building:	\$219,280.00	\$175,000.00	Content:	\$15,000.00	\$7,500.00	<b>TOTAL</b>	\$234,280.00	\$182,500.00		
	<u>Value</u>	<u>Damage</u>													
Building:	\$219,280.00	\$175,000.00													
Content:	\$15,000.00	\$7,500.00													
<b>TOTAL</b>	\$234,280.00	\$182,500.00													
<b>Narrative</b>	<p>This accidental fire was caused by an unspecified electrical short circuit of the fixed wiring. The fire started in the rear of the attic and caused major damage to the entire residence. A fire injury occurred as a result of this fire. An 85-year old female sustained smoke inhalation injuries while sleeping at the time of this fire. She was transported to Baylor Hospital by Rescue 8. This residence had a properly installed operational fire alarm system. The occupant failed to respond to the alarm. Insurance information is unknown at this time. Engine 8 was the first unit to respond to this incident.</p>														

### Three Alarm Fire (Injury)

<b>Date of Fire:</b>	December 13, 2011	<b>Time of Fire</b>	2:25 PM												
<b>Incident Number</b>	2011-243050	<b>Response Time</b>	3 Min. 7 Sec.												
<b>Location</b>	10075 Royal Lane #1047	<b>Service Area</b>	Northeast												
<b>Bldg. Type</b>	2-Story Frame Apartments	<b>Council District</b>	10												
<b>Owner</b>	Sun Colony Associates Ltd.	<b>Injuries (Firefighter/ Civilian)</b>	One Civilian Injury												
<b>Occupant/ Business Name</b>	Terry Doody Sun Colony Apartments														
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	No												
<b>Cause</b>	Careless Use of a Candle														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$3,500,000.00</td> <td style="text-align: right;">\$175,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$20,000.00</td> <td style="text-align: right;">\$13,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$3,520,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$188,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$3,500,000.00	\$175,000.00	Content:	\$20,000.00	\$13,000.00	<b>TOTAL</b>	\$3,520,000.00	\$188,000.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$3,500,000.00	\$175,000.00													
Content:	\$20,000.00	\$13,000.00													
<b>TOTAL</b>	\$3,520,000.00	\$188,000.00													
<b>Narrative</b>	<p>This accidental fire was caused by the careless use of a candle. The candle was knocked over and ignited nearby combustible material. The fire damaged this apartment and the apartment above it. A fire injury occurred as a result of this fire. A 55-year old male sustained minor burns and suffered from smoke inhalation. He was transported to Baylor Hospital by Rescue 74. This apartment had a properly installed fire alarm system that was not working at the time of this fire. This is not an insured loss. Engine 57 was the first unit to respond to this incident.</p>														

### One Alarm Fire (Injury)

<b>Date of Fire:</b>	December 14, 2011	<b>Time of Fire</b>	10:00 AM												
<b>Incident Number</b>	2011-243573	<b>Response Time</b>	2 Min. 29 Sec.												
<b>Location</b>	3330 Webb Chapel Extension #2223	<b>Service Area</b>	Northwest												
<b>Bldg. Type</b>	2-Story Brick Apartments	<b>Council District</b>	6												
<b>Owner</b>	BGWP Warwick LP.	<b>Injuries (Firefighter/ Civilian)</b>	One Civilian Injury												
<b>Occupant/ Business Name</b>	Traci McGrath Plaza Del Lago Apartments														
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	No												
<b>Cause</b>	Careless Smoking														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$600,000.00</td> <td style="text-align: right;">\$10,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$20,000.00</td> <td style="text-align: right;">\$5,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$620,000.00</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$15,000.00</b></td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$600,000.00	\$10,000.00	Content:	\$20,000.00	\$5,000.00	<b>TOTAL</b>	<b>\$620,000.00</b>	<b>\$15,000.00</b>	
	<u>Value</u>	<u>Damage</u>													
Building:	\$600,000.00	\$10,000.00													
Content:	\$20,000.00	\$5,000.00													
<b>TOTAL</b>	<b>\$620,000.00</b>	<b>\$15,000.00</b>													
<b>Narrative</b>	<p>This accidental fire was caused by careless smoking. A lit cigarette was left unattended on a bed in the bedroom. The fire caused severe damage to the bedroom and the contents of the bedroom. A fire injury occurred as a result of this fire. A 42-year old Asian female sustained smoke inhalation injuries. She was transported to Parkland hospital by Rescue 35. This apartment had a properly installed fire alarm system that was not operational at the time of this fire. This is not an insured loss. Engine 43 was the first unit that responded to this incident.</p>														

### Three Alarm Fire

<b>Date of Fire:</b>	December 16, 2011	<b>Time of Fire</b>	3:24 AM												
<b>Incident Number</b>	2011-244797	<b>Response Time</b>	1 Min. 30 Sec.												
<b>Location</b>	1301 Main Street #A	<b>Service Area</b>	Central												
<b>Bldg. Type</b>	4-Story Masonry Commercial	<b>Council District</b>	14												
<b>Owner</b>	Creekbend Properties	<b>Injuries (Firefighter/ Civilian)</b>	N/A												
<b>Occupant/ Business Name</b>	Sabor Tacos Sabor Tacos														
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	Yes												
<b>Cause</b>	Incendiary														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: right;"><u>Value</u></th> <th style="text-align: right;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$1,845,000.00</td> <td style="text-align: right;">\$10,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$100,000.00</td> <td style="text-align: right;">\$10,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$1,945,000.00</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$20,000.00</b></td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$1,845,000.00	\$10,000.00	Content:	\$100,000.00	\$10,000.00	<b>TOTAL</b>	<b>\$1,945,000.00</b>	<b>\$20,000.00</b>	
	<u>Value</u>	<u>Damage</u>													
Building:	\$1,845,000.00	\$10,000.00													
Content:	\$100,000.00	\$10,000.00													
<b>TOTAL</b>	<b>\$1,945,000.00</b>	<b>\$20,000.00</b>													
<b>Narrative</b>	<p>The cause of this fire is incendiary and under investigation at this time. There are no suspects or witnesses at this time. This fire started in the bar area near the front window of this commercial dining occupancy. This restaurant had a properly installed operational fire alarm system. This is an insured loss. Engine 18 was the first unit to respond to this incident.</p>														

### One Alarm Fire (Fatalities)

<b>Date of Fire:</b>	December 18, 2011	<b>Time of Fire</b>	4 :38 PM												
<b>Incident Number</b>	2011-246526	<b>Response Time</b>	8 Min. 15 Sec.												
<b>Location</b>	300 (Block) Town Creek Drive	<b>Service Area</b>	South Central												
<b>Bldg. Type</b>	Vehicle	<b>Council District</b>	4												
<b>Owner</b>	Audra Snow	<b>Injuries (Firefighter/ Civilian)</b>	Two Civilian Fatalities												
<b>Occupant/ Business Name</b>	N/A														
<b>Fire Alarm System</b>	N/A	<b>Operational</b>	N/A												
<b>Cause</b>	Incendiary														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Vehicle:</td> <td style="text-align: right;">\$6,000.00</td> <td style="text-align: right;">\$6,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$0.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$6,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$6,000.00</td> </tr> </tbody> </table>		<u>Value</u>	<u>Damage</u>	Vehicle:	\$6,000.00	\$6,000.00	Content:	\$0.00	\$0.00	<b>TOTAL</b>	\$6,000.00	\$6,000.00		
	<u>Value</u>	<u>Damage</u>													
Vehicle:	\$6,000.00	\$6,000.00													
Content:	\$0.00	\$0.00													
<b>TOTAL</b>	\$6,000.00	\$6,000.00													
<b>Narrative</b>	<p>The cause of this fire is incendiary and under investigation at this time. Suspects have been arrested. The vehicle was destroyed by this fire. The bodies of a nineteen-year old black male, and a twenty-year old black male were discovered in the trunk of this vehicle. The Medical Examiner has determined the causes of death for both as homicide. Insurance information is unknown at this time. The eight minute fifteen second response time is attributed to the responding engine company's failure to activate the on location key. Engine 33 was the first unit to respond to this incident.</p>														

## One Alarm Fire (Injury)

<b>Date of Fire:</b>	December 27, 2011	<b>Time of Fire</b>	3:22 PM										
<b>Incident Number</b>	2011-251993	<b>Response Time</b>	1 Min. 53 Sec.										
<b>Location</b>	2015 Orleans Street	<b>Service Area</b>	Central										
<b>Bldg. Type</b>	1-Story Frame Residence	<b>Council District</b>	2										
<b>Owner</b>	Mike Martel Estate	<b>Injuries (Firefighter/Civilian)</b>	One Firefighter Injury										
<b>Occupant/ Business Name</b>	Chonita Torres												
<b>Fire Alarm System</b>	None	<b>Operational</b>	N/A										
<b>Cause</b>	Combustibles Too Close To Heat Source												
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 20%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$21,210.00</td> <td style="text-align: right;">\$21,210.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$10,000.00</td> <td style="text-align: right;">\$10,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$31,210.00</td> <td style="text-align: right; border-top: 1px solid black;">\$31,210.00</td> </tr> </tbody> </table>		<u>Value</u>	<u>Damage</u>	Building:	\$21,210.00	\$21,210.00	Content:	\$10,000.00	\$10,000.00	<b>TOTAL</b>	\$31,210.00	\$31,210.00
	<u>Value</u>	<u>Damage</u>											
Building:	\$21,210.00	\$21,210.00											
Content:	\$10,000.00	\$10,000.00											
<b>TOTAL</b>	\$31,210.00	\$31,210.00											
<b>Narrative</b>	<p>This accidental fire was caused by combustibles too close to a heat source. A portable electric space heater ignited furniture and destroyed the residence and its contents. A firefighter injury occurred as a result of this fire. A 37-year old male firefighter sustained lower back injuries from hose handling. He was not transported, but was treated at Baylor Hospital. The residence did not have a fire alarm system. Insurance information is unknown at this time. Engine 6 was the first unit to respond to this incident.</p>												

## Two Alarm Fire

<b>Date of Fire:</b>	December 27, 2011	<b>Time of Fire</b>	9:38 PM																
<b>Incident Number</b>	2011-252180	<b>Response Time</b>	3 Min. 3 Sec.																
<b>Location</b>	6834 Larmanda Street #239	<b>Service Area</b>	Northeast																
<b>Bldg. Type</b>	2-Story Brick Apartment	<b>Council District</b>	9																
<b>Owner</b>	Park Lane Terrace Apartments Ltd.	<b>Injuries (Firefighter/Civilian)</b>	N/A																
<b>Occupant/ Business Name</b>	Donneta Kimbrough Park Lane Terrace Apartments																		
<b>Fire Alarm System</b>	Unknown	<b>Operational</b>	Unknown																
<b>Cause</b>	Unspecified Electrical Short Circuit (Non-Fixed Wiring)																		
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;"></th> <th style="width: 35%; text-align: center;"><u>Value</u></th> <th style="width: 35%; text-align: center;"><u>Damage</u></th> <th style="width: 15%;"></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$300,000.00</td> <td style="text-align: right;">\$80,000.00</td> <td></td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$40,000.00</td> <td style="text-align: right;">\$20,000.00</td> <td></td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$340,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$100,000.00</td> <td></td> </tr> </tbody> </table>				<u>Value</u>	<u>Damage</u>		Building:	\$300,000.00	\$80,000.00		Content:	\$40,000.00	\$20,000.00		<b>TOTAL</b>	\$340,000.00	\$100,000.00	
	<u>Value</u>	<u>Damage</u>																	
Building:	\$300,000.00	\$80,000.00																	
Content:	\$40,000.00	\$20,000.00																	
<b>TOTAL</b>	\$340,000.00	\$100,000.00																	
<b>Narrative</b>	<p>This accidental fire was caused by an unspecified electrical short circuit of an extension cord in the living room of this apartment. Fire damage was severe to the apartment and contents. It is unknown if the apartment had a properly installed fire alarm system. This is not an insured loss. Engine 37 was the first unit to respond to this incident.</p>																		

## One Alarm Fire (Injury)

<b>Date of Fire:</b>	December 31, 2011	<b>Time of Fire</b>	2:17 PM												
<b>Incident Number</b>	2011-254483	<b>Response Time</b>	1 Min. 29 Sec.												
<b>Location</b>	2811 Painted Trail	<b>Service Area</b>													
<b>Bldg. Type</b>	1-Story Frame Residence	<b>Council District</b>	8												
<b>Owner</b>	Bonnie Chen	<b>Injuries (Firefighter/Civilian)</b>	One Civilian Injury												
<b>Occupant/ Business Name</b>	Donna Jackson														
<b>Fire Alarm System</b>	Unknown	<b>Operational</b>	Unknown												
<b>Cause</b>	Incendiary														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$62,000.00</td> <td style="text-align: right;">\$45,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$15,000.00</td> <td style="text-align: right;">\$15,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$77,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$60,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$62,000.00	\$45,000.00	Content:	\$15,000.00	\$15,000.00	<b>TOTAL</b>	\$77,000.00	\$60,000.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$62,000.00	\$45,000.00													
Content:	\$15,000.00	\$15,000.00													
<b>TOTAL</b>	\$77,000.00	\$60,000.00													
<b>Narrative</b>	<p>The cause of this fire is incendiary. A suspect has been detained. The residence sustained major damage to the structure and its contents. A fire injury occurred as a result of this fire. A 35-year old black female sustained smoke inhalation injuries. She was transported to Parkland hospital by Rescue 46. It is unknown if this residence had a properly installed operational fire alarm system. Insurance information is unknown at this time. Engine 40 was the first unit to respond to this incident.</p>														