

Memorandum



Date: November 11, 2011

To: Members of the Public Safety Committee

Subject: Administrative (Fire) Reports

The Public Safety Committee will be briefed on the September and October Administrative (Fire) Reports on Monday, November 14, 2011.



A.C. Gonzalez
First Assistant City Manager

Attachment

cc: Honorable Mayor and Members of the City Council
Mary Suhm, City Manager
Rosa Rios, Acting City Secretary
Thomas P. Perkins, Jr., City Attorney
Craig D. Kinton, City Auditor
C. Victor Lander, Administrative Judge
A.C. Gonzalez, First Assistant City Manager
Ryan S. Evans, Assistant City Manager
Jill A. Jordan, P.E., Assistant City Manager
Forest E. Turner, Assistant City Manager
Joey Zapata, Interim Assistant City Manager
Jeanne Chipperfield, Chief Financial Officer
Frank Libro, Public Information Office
Helena Stevens-Thompson, Assistant to the City Manager

Public Safety Committee

Fire Report

September 2011

DATE	ADDRESS	COUNCIL DISTRICT	TYPE	CAUSE	LOSS/INSURED?	ALARMS
1. 09/01/11	5425 Gaston Avenue #210	District 14	2-Story Brick Apartments	Unattended Cooking	\$8,000 No	1 Alarm (Injuries)
2. 09/11/11	9680 Timberline Drive #228	District 6	2-Story Frame Apartments	Unspecified Electrical Short Circuit	\$570,000 Yes	4 Alarms (Injury)
3. 09/14/11	4444 W. Ledbetter Drive	District 3	1-Story Metal Commercial	Equipment Malfunction	\$500,000 Yes	3 Alarms
4. 09/16/11	2631 John West Road #1104	District 7	2-Story Frame Apartments	Unattended Cooking	\$50 No	1 Alarm (Injury)
5. 09/18/11	331 W. Woodin Boulevard	District 3	1-Story Frame Residence	Lightning Strike	\$35,000 Yes	1 Alarm (Injuries)
6. 09/27/11	9030 Markville Drive #3734	District 10	3-Story Brick Apartments	Unspecified electrical Short Circuit.	\$300,000 Yes	4 Alarms
7. 09/28/11	3727 Conway Street #255	District 4	2-Story Frame Apartments	Unattended Cooking	\$1,500 No	1 Alarm (Injury)

One Alarm Fire (Injuries)

Date of Fire:	September 1, 2011	Time of Fire	3:42 AM												
Incident Number	2011-172428	Response Time	2 Min. 16 Sec.												
Location	5425 Gaston Avenue #210	Service Area	Central												
Bldg. Type	2-Story Brick Apartments	Council District	14												
Owner	Brad and Kim Silveira	Injuries (Firefighter/ Civilian)	Two Civilian Injuries												
Occupant/ Business Name	Sharon Jones and Lewis Jackson Angora Apartments														
Fire Alarm System	Yes	Operational	Yes												
Cause	Unattended Cooking														
Value/ Damage Estimate	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;"></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$638,380.00</td> <td style="text-align: right;">\$5,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$3,000.00</td> <td style="text-align: right;">\$3,000.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$641,380.00</td> <td style="text-align: right; border-top: 1px solid black;">\$8,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$638,380.00	\$5,000.00	Content:	\$3,000.00	\$3,000.00	TOTAL	\$641,380.00	\$8,000.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$638,380.00	\$5,000.00													
Content:	\$3,000.00	\$3,000.00													
TOTAL	\$641,380.00	\$8,000.00													
Narrative	<p>This unintentional fire was caused by unattended cooking. The fire caused major damage to the kitchen of this apartment unit. Two civilian injuries occurred as a result of this fire. A 52-year old black female sustained a laceration to her right arm and smoke inhalation injuries attempting to escape through a window. She was transported to Parkland Hospital by Rescue 8. A 52-year old black male sustained smoke inhalation injuries and was transported to Parkland Hospital by Rescue 19. This apartment was equipped with a properly installed operational fire alarm system. It is unknown if the fire alarm system warned the occupants of the fire. This is not an insured loss. Engine 19 was the first unit to respond to this incident.</p>														

Four Alarm Fire (Injury)

Date of Fire:	September 11, 2011	Time of Fire	10:26 AM												
Incident Number	2011-180117	Response Time	3 Min. 6 Sec.												
Location	9680 Timberline Drive #228	Service Area	Northwest												
Bldg. Type	2-Story Frame Apartments	Council District	6												
Owner	BH Clubview NW LLC	Injuries (Firefighter/ Civilian)	One Firefighter Injury												
Occupant/ Business Name	Rosa Reyes Northwest Crossing Apartments														
Fire Alarm System	Unknown	Operational	N/A												
Cause	Unspecified Electrical Short Circuit Fixed Wiring														
Value/ Damage Estimate	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: right;"><u>Value</u></th> <th style="text-align: right;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$1,368,000.00</td> <td style="text-align: right;">\$500,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$70,000.00</td> <td style="text-align: right;">\$70,000.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right;">\$1,438,000.00</td> <td style="text-align: right;">\$570,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$1,368,000.00	\$500,000.00	Content:	\$70,000.00	\$70,000.00	TOTAL	\$1,438,000.00	\$570,000.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$1,368,000.00	\$500,000.00													
Content:	\$70,000.00	\$70,000.00													
TOTAL	\$1,438,000.00	\$570,000.00													
Narrative	<p>This unintentional fire was caused by an unspecified electrical short circuit of the fixed wiring of this apartment building. A total of seven apartment units were damaged by this fire. A firefighter injury occurred as a result of this fire. A 50-year old white male suffered from heat exhaustion. He was transported to Parkland Hospital by Rescue 47. It is unknown if this apartment had a properly installed operational fire alarm system. (Capt. Mathews, please have someone determine whether there was a properly installed fire alarm system.) This is an insured loss. Engine 43 was the first unit to respond to this incident.</p>														

Three Alarm Fire

Date of Fire:	September 14, 2011	Time of Fire	5:21 PM
Incident Number	2011-182449	Response Time	4 Min. 9 Sec.
Location	4444 W. Ledbetter Dr.	Service Area	Southwest
Bldg. Type	1-Story Metal Commercial	Council District	3
Owner	Solo Cup Corporation	Injuries (Firefighter/ Civilian)	N/A
Occupant/ Business Name	Solo Cup Corporation		
Fire Alarm System	Yes	Operational	Yes
Cause	Equipment Malfunction		
Value/ Damage Estimate	Value	Damage	
	Building: \$60,359,000.00	\$300,000.00	
	Content: \$200,000.00	\$200,000.00	
	TOTAL \$60,559,000.00	\$500,000.00	
Narrative	<p>This unintentional fire was caused by a waxing machine malfunction during its startup process. The fire spread up to the ceiling, then spread laterally and entered a concealed space between the ceiling and the roof. The fire caused extensive damage to the building and its contents. This commercial occupancy had a properly installed operational fire alarm system that warned the occupants of the fire and aided in their escape. The property also had an operational fire sprinkler system. This is an insured loss. Engine 52 was the first unit to respond to this incident.</p>		

One Alarm Fire (Injury)

Date of Fire:	September 16, 2011	Time of Fire	7:12 PM												
Incident Number	2011-183872	Response Time	3 Min. 50 Sec.												
Location	2631 John West Road #1104	Service Area	Northeast												
Bldg. Type	2-Story Frame Apartments	Council District	7												
Owner	Carleton La Prada Ltd.	Injuries (Firefighter/ Civilian)	One Civilian Injury												
Occupant/ Business Name	Jennifer Bradley Traymore Eastfield Apartments														
Fire Alarm System	Yes	Operational	Yes												
Cause	Unattended Cooking														
Value/ Damage Estimate	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$4,350,000.00</td> <td style="text-align: right;">\$50.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$5,000.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$4,355,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$50.00</td> </tr> </tbody> </table>				<u>Value</u>	<u>Damage</u>	Building:	\$4,350,000.00	\$50.00	Content:	\$5,000.00	\$0.00	TOTAL	\$4,355,000.00	\$50.00
	<u>Value</u>	<u>Damage</u>													
Building:	\$4,350,000.00	\$50.00													
Content:	\$5,000.00	\$0.00													
TOTAL	\$4,355,000.00	\$50.00													
Narrative	<p>This unintentional fire was caused by unattended cooking. The fire caused minor damage to the kitchen of this apartment unit. One civilian injury occurred as a result of this fire. A 29-year old black female sustained second and third degree burns to her legs when she tried to dispose of the burning pan of grease. She was transported to Parkland Hospital by Rescue 39. This apartment had a properly installed operational fire alarm system that warned the occupant of the fire. This is not an insured loss. Engine 53 was the first unit to respond to this incident.</p>														

One Alarm Fire (Injuries)

Date of Fire:	September 18, 2011	Time of Fire	11:01 PM												
Incident Number	2011-185752	Response Time	2 Min. 17 Sec.												
Location	331 W. Woodin Boulevard	Service Area	Southwest												
Bldg. Type	1-Story Frame Residence	Council District	3												
Owner	Domingo Mendez	Injuries (Firefighter/ Civilian)	Three Civilian Injuries												
Occupant/ Business Name	Domingo Mendez, Jr.														
Fire Alarm System	Unknown	Operational	N/A												
Cause	Lightning Strike														
Value/ Damage Estimate	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 20%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$91,700.00</td> <td style="text-align: right;">\$30,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$5,000.00</td> <td style="text-align: right;">\$5,000.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$96,700.00</td> <td style="text-align: right; border-top: 1px solid black;">\$35,000.00</td> </tr> </tbody> </table>		<u>Value</u>	<u>Damage</u>	Building:	\$91,700.00	\$30,000.00	Content:	\$5,000.00	\$5,000.00	TOTAL	\$96,700.00	\$35,000.00		
	<u>Value</u>	<u>Damage</u>													
Building:	\$91,700.00	\$30,000.00													
Content:	\$5,000.00	\$5,000.00													
TOTAL	\$96,700.00	\$35,000.00													
Narrative	<p>This fire was caused by lightning igniting a natural gas leak causing moderate damage to the structure and contents. This fire also caused damage to a shed on an adjacent property. Three civilian injuries occurred as a result of this fire. A 33-year old Hispanic male sustained multiple burns to 45% of his body. He was transported to Parkland Hospital by Rescue 25. A 26-year old Hispanic female sustained multiple burns to 60% of her body. A 5-year old Hispanic male sustained multiple burns to 40% of his body. They were transported to Parkland Hospital by Rescue 38. It is unknown if this residence had a properly installed operational fire alarm system. This is an insured loss. Engine 33 was the first unit to respond to this incident.</p>														

Four Alarm Fire

Date of Fire:	September 27, 2011	Time of Fire	11:48 PM												
Incident Number	2011-191824	Response Time	5 Min.												
Location	9030 Markville Drive #3734	Service Area	Northeast												
Bldg. Type	3-Story Brick Apartments	Council District	10												
Owner	Falls Highpoint SPE7 LLC.	Injuries (Firefighter/Civilian)	N/A												
Occupant/ Business Name	Jamwell Kamau The Falls at Highpoint														
Fire Alarm System	Yes	Operational	Yes												
Cause	Unspecified Electrical Short Circuit														
Value/ Damage Estimate	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 50%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building: \$13,250,000.00</td> <td></td> <td style="text-align: right;">\$250,000.00</td> </tr> <tr> <td>Content: \$250,000.00</td> <td></td> <td style="text-align: right;">\$50,000.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right;">\$13,500,000.00</td> <td style="text-align: right;">\$300,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building: \$13,250,000.00		\$250,000.00	Content: \$250,000.00		\$50,000.00	TOTAL	\$13,500,000.00	\$300,000.00	
	<u>Value</u>	<u>Damage</u>													
Building: \$13,250,000.00		\$250,000.00													
Content: \$250,000.00		\$50,000.00													
TOTAL	\$13,500,000.00	\$300,000.00													
Narrative	<p>This unintentional fire was caused by an unspecified short circuit of the fixed wiring in the attic above this apartment. The fire destroyed a total of five apartments in this building. The apartment building was equipped with a properly installed operational fire alarm system. It is unknown if it warned the occupants of the fire. This is an insured loss. Engine 22 was the first unit to respond to this incident.</p>														

One Alarm Fire (Injury)

Date of Fire:	September 28, 2011	Time of Fire	3:41 AM												
Incident Number	2011-191898	Response Time	4 Min. 46 Sec.												
Location	3727 Conway Street #255	Service Area	South Central												
Bldg. Type	2-Story Frame Apartments	Council District	4												
Owner	Southcrest LTD.	Injuries (Firefighter/ Civilian)	One Civilian Injury												
Occupant/ Business Name	Keldrick Lewis Southwest Apartments														
Fire Alarm System	Yes	Operational	Yes												
Cause	Unattended Cooking														
Value/ Damage Estimate	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$2,524,660.00</td> <td style="text-align: right;">\$1,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$2,000.00</td> <td style="text-align: right;">\$500.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$2,526,660.00</td> <td style="text-align: right; border-top: 1px solid black;">\$1,500.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$2,524,660.00	\$1,000.00	Content:	\$2,000.00	\$500.00	TOTAL	\$2,526,660.00	\$1,500.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$2,524,660.00	\$1,000.00													
Content:	\$2,000.00	\$500.00													
TOTAL	\$2,526,660.00	\$1,500.00													
Narrative	<p>This unintentional fire was caused by unattended cooking. The occupant fell asleep and left a pan of grease cooking on their stove. Fire caused moderate damage to the kitchen and its contents. One civilian injury occurred as a result of this fire. A 39-year old black male sustained second degree burns to his right forearm while attempting to extinguish the fire. He was treated at the scene by Rescue 33 and released. This apartment had a properly installed operational fire alarm system that warned the occupant of the fire. This is not an insured loss. Engine 33 was the first unit to respond to this incident.</p>														

Public Safety Committee

Fire Report

October 2011

DATE	ADDRESS	COUNCIL DISTRICT	TYPE	CAUSE	LOSS/INSURED?	ALARMS
1. 10/07/11	555 S. Lamar St.	District 2	23-Story New Concrete Hotel	Spontaneous Combustion Oily Rags	\$800,000 Yes	2 Alarm (Injury)
2. 10/15/11	10010 Whitehurst Dr.	District 10	2-Story Frame Apartments	Unspecified Electrical Short Circuit	\$367,000 Unknown	2 Alarms
3. 10/25/11	10582 Spangler Rd.	District 6	1-Story metal commercial	Under Investigation	\$100,000 Unknown	2 Alarms
4. 10/27/11	2700 Canton St.	District 2	4-Story Old Brick Apartments	False Alarm	\$0 Unknown	2 Alarms
5. 10/28/11	3100 S. Lamar St.	District 7	2-Story Old Brick Apartments	Under Investigation	\$60,000 Unknown	3 Alarms
6. 10/29/11	6716 Sebring Dr.	District 8	1-Story Old Brick Dwelling	Unspecified Electrical Short Circuit	\$5,500 Unknown	1 Alarm (Injury)

Two Alarm Fire (Injury)

Date of Fire:	October 07, 2011	Time of Fire	10:33 PM												
Incident Number	2011-198864	Response Time	3 Min. 12 Sec.												
Location	555 S. Lamar St.	Service Area	Central												
Bldg. Type	23-Story New Concrete Hotel	Council District	2												
Owner	City of Dallas	Injuries (Firefighter/ Civilian)	One Firefighter Injury												
Occupant/ Business Name	City of Dallas														
Fire Alarm System	Yes	Operational	Yes												
Cause	Spontaneous Combustion / Oily Rags														
Value/ Damage Estimate	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$23,703,920.00</td> <td style="text-align: right;">\$800,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$0.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$23,703,920.00</td> <td style="text-align: right; border-top: 1px solid black;">\$800,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$23,703,920.00	\$800,000.00	Content:	\$0.00	\$0.00	TOTAL	\$23,703,920.00	\$800,000.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$23,703,920.00	\$800,000.00													
Content:	\$0.00	\$0.00													
TOTAL	\$23,703,920.00	\$800,000.00													
Narrative	<p>This unintentional fire was caused by spontaneous combustion of oily rags. The fire started in a plastic container on the outside area on the 4th floor/pool area. Melted plastic dripped between the floor and sub-floor causing a heat buildup. High heat resulted in breakage of the floor. A firefighter received an injury to his hand and was transported to Baylor Hospital by Rescue 19. Engine 18 was the first unit to arrive at the scene.</p>														

Two Alarm Fire

Date of Fire:	October 15, 2011	Time of Fire	2:49 AM												
Incident Number	2011-204079	Response Time	2 Min. 1 Sec.												
Location	10010 Whitehurst Dr.	Service Area	Northeast												
Bldg. Type	2-Story Frame Apartments	Council District	10												
Owner	Wak / Sh LLC	Injuries (Firefighter/ Civilian)	N/A												
Occupant/ Business Name	Summer Hill Apartments														
Fire Alarm System	Yes	Operational	Yes												
Cause	Unspecified Electrical Short Circuit Fixed Wiring														
Value/ Damage Estimate	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: right;"><u>Value</u></th> <th style="text-align: right;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$4,835,800.00</td> <td style="text-align: right;">\$350,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$0.00</td> <td style="text-align: right;">\$17,000.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$4,835,800.00</td> <td style="text-align: right; border-top: 1px solid black;">\$367,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$4,835,800.00	\$350,000.00	Content:	\$0.00	\$17,000.00	TOTAL	\$4,835,800.00	\$367,000.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$4,835,800.00	\$350,000.00													
Content:	\$0.00	\$17,000.00													
TOTAL	\$4,835,800.00	\$367,000.00													
Narrative	<p>This accidental fire was caused by an unspecified electrical short circuit of the fixed wiring of this apartment building. Neighbors and the tenant reported seeing smoke coming from the soffits of the building. The apartment manager knocked on apartment doors alerting tenants of the fire. First in firefighters reported light smoke but no fire in the apartment until they penetrated the ceiling and found heavy smoke and fire. The cause of the fire is unspecified electrical short (fixed wiring). Engine 57 was the first unit to arrive at the fire scene.</p>														

Two Alarm Fire

Date of Fire:	October 25, 2011	Time of Fire	11:47 PM												
Incident Number	2011-211279	Response Time	6 min. 46 sec.												
Location	10582 Spangler Rd.	Service Area	Northwest												
Bldg. Type	1-Story Metal Commercial	Council District	6												
Owner	E&M Realty Holdings, LLC.	Injuries (Firefighter/ Civilian)	N/A												
Occupant/ Business Name	Living Earth														
Fire Alarm System	No	Operational	N/A												
Cause	Under Investigation														
Value/ Damage Estimate	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$100,000.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$250,000.00</td> <td style="text-align: right;">\$100,000.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$350,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$100,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$100,000.00	\$0.00	Content:	\$250,000.00	\$100,000.00	TOTAL	\$350,000.00	\$100,000.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$100,000.00	\$0.00													
Content:	\$250,000.00	\$100,000.00													
TOTAL	\$350,000.00	\$100,000.00													
Narrative	<p>The cause of this fire is under investigation. This is commercial property for lumber, mulch and natural fertilizers. There were several piles of wood, lumber and mulch on fire.</p>														

Two Alarm Fire

Date of Fire:	October 27, 2011	Time of Fire	9:11 PM												
Incident Number	2011-212494	Response Time	2 Min. 27 Sec.												
Location	2700 Canton St.	Service Area	Central												
Bldg. Type	4-Story Old Brick Apartments	Council District	2												
Owner	Westdale Adams Hats LTD	Injuries (Firefighter/ Civilian)	N/A												
Occupant/ Business Name	Adams Hat Building														
Fire Alarm System	Yes	Operational	Unknown												
Cause	False Alarm														
Value/ Damage Estimate	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;"></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$3,919,300.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$0.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$3,919,300.00</td> <td style="text-align: right; border-top: 1px solid black;">\$0.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$3,919,300.00	\$0.00	Content:	\$0.00	\$0.00	TOTAL	\$3,919,300.00	\$0.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$3,919,300.00	\$0.00													
Content:	\$0.00	\$0.00													
TOTAL	\$3,919,300.00	\$0.00													
Narrative	<p>This was a false alarm due to an unattended smoke machine located in apartment 304. The tenant turned the machine on and left to pick up a friend. The smoke machine produced artificial smoke throughout the apartment.</p>														

Three Alarm Fire

Date of Fire:	October 28, 2011	Time of Fire	2:13 AM												
Incident Number	2011-212917	Response Time	2 Min. 12 Sec.												
Location	3100 S. Lamar St.	Service Area	Southeast												
Bldg. Type	2-Story Old Brick Apartment	Council District	7												
Owner	Wendy Chen	Injuries (Firefighter/ Civilian)	N/A												
Occupant/ Business Name	Gloria White / South Cliff Apartments														
Fire Alarm System	No	Operational	N/A												
Cause	Under Investigation														
Value/ Damage Estimate	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$316,000.00</td> <td style="text-align: right;">\$50,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$0.00</td> <td style="text-align: right;">\$10,000.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$316,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$60,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$316,000.00	\$50,000.00	Content:	\$0.00	\$10,000.00	TOTAL	\$316,000.00	\$60,000.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$316,000.00	\$50,000.00													
Content:	\$0.00	\$10,000.00													
TOTAL	\$316,000.00	\$60,000.00													
Narrative	<p>This fire is still under investigation. Engine 6 was the first arriving company and reported smoke from apartment # 109 which spread to several adjacent units. There were no reported injuries.</p>														

1 Alarm Fire (Injury)

Date of Fire:	October 29, 2011	Time of Fire	12:41 AM												
Incident Number	2011-213280	Response Time	4 Min. 47 Sec.												
Location	6716 Sebring Dr.	Service Area	South Central												
Bldg. Type	1 Story-Old Brick Dwelling	Council District	8												
Owner	Thomas Gayfield	Injuries (Firefighter/ Civilian)	Civilian												
Occupant/ Business Name	Thomas Gayfield														
Fire Alarm System	Unknown	Operational	N/A												
Cause	Unspecified Electrical Short														
Value/ Damage Estimate	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$25,000.00</td> <td style="text-align: right;">\$5,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$10,000.00</td> <td style="text-align: right;">\$500.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$35,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$5,500.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$25,000.00	\$5,000.00	Content:	\$10,000.00	\$500.00	TOTAL	\$35,000.00	\$5,500.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$25,000.00	\$5,000.00													
Content:	\$10,000.00	\$500.00													
TOTAL	\$35,000.00	\$5,500.00													
Narrative	<p>This fire was the result of an unspecified electrical short in the insulation of a power-strip in a bedroom of this dwelling. The fire spread throughout the bedroom and caused one civilian injury—second-degree burns to his face and hands. The victim, a 17 year old black male also suffered from smoke inhalation. Engine 54 was the first responding unit.</p>														