

ASSESSMENT OF 60 RANDOMLY SELECTED PATROL VEHICLES

Make And Year	Unit Number	Mileage	Exterior	Interior	Overall Assessment
CV-2000	0-316	131,768	Worn, back bumper broken up	Worn seats, smelly	Bad
CV-2000	0-373	131,232	Worn	Seats worn and stained	Worn out
CV-2000	0-384	129,953	Worn paint	Holes in seats, very worn	Bad
CV-2000	0-371	123,074	Worn, headlight out	Worn seats, no a/c	Worn out
CV-2000	0-350	122,698	Worn with lots of dings	Worn seats, door panel broken	Bad
CV-1998	8-009	121,490	Worn		Bad
CV-2000	0-435	121,192	Worn	Stained and torn seat, smelly	Bad
CV-1998	8-116	120,418	Very poor	Holes in seat, very worn	Worn out
CV-1998	8-210	116,433	Cracked back bumper	Holes in seat, stained and worn	Worn out
CV-1998	8-096	116,040	Cracked back bumper	Holes in seat, stained and smelly	Worn out
CV-2000	0-175	116,015	Worn with faded paint	Hole in seat, floor covering torn, smelly	Bad
CV-2000	0-423	112,253	Worn	Seats replaced, door panel broken	Marginal
CV-2000	0-406	112,077	Worn	Hole in seat, stained and smelly	Very worn
CAP-1995	5-159	109,506	Very poor	Very poor, back window broken	Should be retired
CV-2000	0-124	109,500	Back bumper busted up	Very worn and dirty seats	Bad
CV-2000	0-358	107,939	OK	Holes in seats, dirty and soiled	Bad
CV-2000	0-394	107,580	Worn	Holes in seat, stained and smelly	Worn, burns oil
CV-2001	1-090	106,070	Worn	Dirty with holes in seats	Bad
CV-2000	0-035	103,136	Worn	Hole in seat, worn and dirty	Bad
CV-2001	1-069	102,290	Worn	Seats worn and stained	Worn
CV-2001	1-043	101,688	Worn	Worn, new front seats, roof lining torn	Worn

ASSESSMENT OF 60 RANDOMLY SELECTED PATROL VEHICLES

Make And Year	Unit Number	Mileage	Exterior	Interior	Overall Assessment
CV-1998	8-053	101,060	Worn	Very worn and dirty seats	Worn
CAP-1995	5-131	98,587	Faded blue, worn	Holes in seat, very worn	Worn out
CAP-1995	5-022	98,467	OK	Very worn and dirty seats	Very worn
CAP-1995	5-106	96,589	Faded blue, worn	Very worn and dirty seats	Worn out
CV-2001	1-096	96,093	OK, somewhat worn, new transmission	Seats worn and stained	Worn
CV-2000	0-271	92,908	Old style emergency lights	Holes in seats	Bad
CV-2001	1-070	92,562	Worn, mirrors don't work	Seats worn and stained	Worn
CV-2001	1-072	91,438	Old style emergency lights	Hole in seats, door panel broken, no gasoline button	Bad
CV-2001	1-066	90,947	Worn	Holes in seats	Bad
CV-2000	0-260	87,979	Worn	Hole in seat, stained and smelly	Very worn
CV-1997	7-173	87,033	OK	OK	OK
CV-2001	1-092	82,271	OK	Holes in seats, very worn	Bad
CV-2000	0-131	80,242	OK	Very worn and dirty seats	Very worn
CV-2000	0-042	77,365	Front door won't close tight	Worn with soiled seats, smelly	Worn
CV-2001	1-134	73,340	OK	Worn, stained and smelly	Significant wear
CAP-1994	4-068	69,971	OK	Worn, stained seats	Reserve vehicle
CV-2000	0-072	62,221	Hail damage	Holes in seat, stained and dirty	Very worn
CV-2000	0-426	59,415	OK	Worn, stained seats	Worn
CV-2001	1-142	59,252	OK	Starting to wear, seats worn	OK
CV-2001	1-132	56,946	Beginning to wear	Worn, slight hole, stained	Beginning to show wear
CV-2000	0-198	53,822	OK	OK	OK
CV-2001	1-155	46,680	OK	Seats beginning to wear	OK
CV-2001	1-173	45,527	OK	Starting to wear, seats worn	OK
CV-2001	1-156	43,037	OK	Starting to wear, seats worn	OK

ASSESSMENT OF 60 RANDOMLY SELECTED PATROL VEHICLES

Make And Year	Unit Number	Mileage	Exterior	Interior	Overall Assessment
CV-2001	1-162	39,233	OK	OK	OK
CV-2003	3-008	33,691	OK	OK	OK
CV-2001	1-172	31,990	OK	OK	OK
CV-2001	1-164	26,861	OK	OK	OK
CV-2003	3-017	24,072	Good	OK	Good
CV-2003	3-034	23,293	Good	Good	Good
CV-2003	3-035	21,359	OK	OK	OK
CV-2003	3-045	19,020	Good	OK	OK
CV-2003	3-056	16,365	Good	Good	Good
CV-2003	3-042	15,645	Good	Good	Good
CV-2003	3-053	15,214	Good	Good	Good
CV-2003	3-058	13,000	Good	Good	Good
CV-2001	1-167	12,244	Good	Good	Good
CV-2003	3-069	10,990	OK	OK	OK
CV-2003	3-074	10,818	New	Good	Good
CV-2003	3-062	2,763	Good	New	New